

FIG-1

If the external flexible cable or cord of this luminaire is damaged, it shall be exclusively replaced by the manufacturer or his service agent or a similar qualified person in order to avoid a hazard.




FIG-2-A
Concrete

FIG-2-B

wood board
Please make sure
the thickness of the
wood board no less
than 5mm





FIG-3



Torque: 3-3.5kgf.cm

Torque:
3.5-4kgf.cm





FIG-5

